















<p>1</p>	<p style="text-align: center;">NG</p>  <p style="text-align: center;">NG Condition: Waist belt with metal buckle</p>	<p style="text-align: center;">OK</p>  <p style="text-align: center;">OK Condition: Wear soft waist belts</p>
<p>2</p>	 <p style="text-align: center;">NG Condition: Watch on wrist</p>	 <p style="text-align: center;">OK Condition: Do not wear watch while working</p>
<p>3</p>	<p style="text-align: center;">NG</p>  <p style="text-align: center;">NG Condition: Ring on fingers</p>	<p style="text-align: center;">OK</p>  <p style="text-align: center;">OK Condition: Don't wear any ring on fingers while working</p>
<p>4</p>	 <p style="text-align: center;">NG Condition: Metal ring (Karaa) on wrist</p>	 <p style="text-align: center;">OK Condition: Do not wear any Karaa on wrist while working</p>
<p>5</p>	<p style="text-align: center;">NG</p>  <p style="text-align: center;">NG Condition: Key bunch clamped on belt loop</p>	<p style="text-align: center;">OK</p>  <p style="text-align: center;">OK Condition: Do not hang key bunches on belt loop to avoid contact with vehicle body</p>
<p>6</p>	 <p style="text-align: center;">NG Condition: Underbody inspection without helmet</p>	 <p style="text-align: center;">OK Condition: Always wear helmet while inspection underbody</p>
<p>7</p>	<p style="text-align: center;">NG</p>  <p style="text-align: center;">NG Condition: Not wearing safety shoes</p>	<p style="text-align: center;">OK</p>  <p style="text-align: center;">NG Condition: Always wear safety shoes during inspection</p>